# PT0439.10 Cable

WX-013-0218

More information on the website
mirror.radwag.com/en/info,w1,3QO



The drawings, photos and graphics used are for illustrative purposes only.

## Overview

PT0439 cable is used for connecting PUE 5, PUE HY10, PUE HX7 and PUE H315 stainless steel terminals and indicators via RS 232.

Standard length: 10 m

## Compatible with (Additional Fee)

PUE 5 Weighing Terminal
PUE HX7 Weighing Terminal
PUE HY10 Weighing Terminal
PUE H315 Weighing Terminal