


RS 232 / RS 485 Cables

Compatibility of weighing instruments and indicators, and integration with peripheral equipment.



PT0094



PT0019



P0151



PT0348



PT0326

Compatible With

P0151

- Weighing instruments with PUE C31 indicator
- Weighing instruments with PUE 7.1 indicator
- PUE C31 indicator
- PUE 7.1 indicator

P0261

- Weighing instruments with PUE C/31H indicator
- Weighing instruments with PUE C/31H/Z indicator
- PUE C/31H indicator
- PUE C/31H/Z indicator

PT0019

- Weighing instruments with PUE C41H indicator
- Weighing instruments with PUE HY indicator
- Weighing instruments with PUE 5.15 (PUE 5.19) indicator
- PUE C41H indicator
- PUE 5.15 (PUE 5.19) indicator
- PUE HY indicator

P0108

- Weighing instruments with PUE C31 indicator
- Weighing instrument with PUE 7.1 indicator
- PUE C31 indicator
- PUE 7.1 indicator

P0259

- Weighing instruments with PUE C/31H indicator
- Weighing instruments with PUE C/31H/Z indicator
- PUE C/31H indicator
- PUE C/31H/Z indicator

PT0020

- Weighing instruments with PUE C41H indicator
- Weighing instruments with PUE 5.15 (5.19) indicator
- Weighing instruments with PUE HY indicator
- PUE C41H indicator
- PUE 5.15 (5.19) indicator
- PUE HY indicator

PT0167

- Weighing instruments with PUE 7.1 indicator
- Weighing instruments with PUE C32 indicator
- 3Y and 4Y balances

PT0347

- HRP Platforms
- MWSH Weighing module
- MWLH Weighing module

PT0348

- HRP Platforms
- MWSH Weighing module
- MWLH Weighing module

Technical Specifications

	P0151	P0261	PT0019	P0108
Connector	weighing instrument (PUE C/31 indicator) - Epson printer	weighing instrument (PUE C/31H indicator) - Epson printer	weighing instrument (PUE C/41H, PUE HY, PUE 5 indicator) - Epson printer	weighing instrument (PUE C/31 indicator) - computer
Length		Standard 2m Optional (additional charge) 5m or 10m	Standard 2m Optional (additional charge) 5m or 10m	1,7 m

	P0259	PT0020	PT0167	PT0347
Connector	weighing instrument (PUE C/31/H indicator) - computer	weighing instrument (PUE C/41H, PUE HY, PUE 5 indicator) - computer	weighing instrument (15-pin connector) – PC computer (9-pin connector)	balance (HRP, MWSH, MWLH) – HY10, PUE5 indicator
Length	Standard 2 m Optional (additional charge) 5m lub 10m	Standard 2 m Optional (additional charge) 5m lub 10m	Standard 2 m Optional (additional charge) 5m lub 10m	2 meters 5 meters 10 meters

	P0259	PT0326	PT0022
Connector	balance (HRP, MWSH, MWLH) – computer with a connector for SYS-1544-2415-T3-HRP power supply	PUE C/31H indicator – PUE5, HY10 indicator.	balance (PUE C/41H, PUE HY10, PUE 5 indicator) - ZEBRA printer
Length	2 meters 5 meters 10 meters	Standard 2m Optional (additional charge) 5m or 10m	Standard 2m Optional (additional charge) 5m or 10m

Dimensions

