



EXTERNAL BUTTONS "TARA - PRINT"



Buttons for remote release of functions TARE and PRINT.
Cable connection to the weighing instrument.
Cable length 1,5m.
Casing out of plastics.

Buttons are offered in below specified versions:
-Pt0021 for PUE C41H indicator, PUE HY indicator
-P0168 for terminal TMC



Specification:

Mechanical durability	>1000000 weighing cycles
Operation frequency	<3600 cycles / hour
Cable length	1,5m standard
Working temperature	-25° ÷ +40°C
IP rating	IP 54
Dimensions	120 × 80 × 56